

SHUMMIT Mob/Whatsapp: +86 13410541523 Email : <u>ruby@shumatt.com</u> © 2024 Shenzhen Shumatt Technology Co., Ltd TIMM

Timm

Tel: +8675523215133 Website : <u>www.shumatt.com</u>

Innit

TIMM

TIMM

Inniti

3h

SH

SH

=h

当ち

SH

TIMM

ATT

SHUMAT

SHUMAT

SHUMA

Infit

Unit

UMAT

095030-6540 Injector Valve Stem G2 Series Technical File SHUMATT

EHUM

SHUMAT

SHUMMI

SHUMAT

SHUMFT

3h

AUMAT

Content

1 00E020 EE40 Injector Value Stem Introduction	2
1. 095030-6540 Injector Valve Stem Introduction 1.1. 095030-6540 Injector Valve Stem Basic Information	.2
1.2. 095030-6540Injector Valve Stem Common Part Number	
1.3. 095030-6540 Injector Valve Stem Parameter	.2
1.4. 095030-6540 Injector Valve Stem Specifications and Dimensions	
1.5. 095030-6540 Injector Valve Stem Quality Control	
1.6. 095030-6540 Injector Valve Stem Customized Service	.3
1.7. 095030-6540 Injector Valve Stem Package List&Size	.3
1.8. 095030-6540Injector Valve Stem Testing Standard and Certificate	
1.9. 095030-6540Injector Valve Stem Warranty Description	.5
2. 095030-6540 Injector Valve Stem Technical Support	.6
2.1. 095030-6540 Injector Valve Stem Measuring Tools	.6
2.2. 095030-6540 Injector Valve Stem Measuring Steps	.7
2.3. 095030-6540 Injector Valve Stem Installation Precautions	.7
2.4. Reasons For 095030-6540 Injector Valve Stem Not Working Normally	
2.5. Causes of 095030-6540 Injector Valve Stem Being Damaged	.8
2.6. 095030-6540 Injector Valve Stem Storage Standard	.9
2.7. 095030-6540 Injector Valve Stem Technical Support Obtaining Methods1	10
3. 095030-6540 Injector Valve Stem Purchase and Delivery1	10
3.1. 095030-6540 Injector Valve Stem Purchase Payment Term1	10
3.2. 095030-6540 Injector Valve Stem Main Sales Markets1	10
3.3. 095030-6540 Injector Valve Stem Declaration Requirements1	
3.4. 095030-6540 Injector Valve Stem Shipping Ways1	10
3.5. 095030-6540 Injector Valve Stem Lead time1	10
3.6. 095030-6540 Injector Valve Stem Logistics Time for Destination Out of China's Areas1	
3.7. 095030-6540 Injector Valve Stem Packing1	
4. Company Information	13
4.1. Company Introduction1	
4.2. Sale-men Contact Information1	
5. Copyright Statement	

Mob/Whatsapp: +86 13410541523 Email : ruby@shumatt.com © 2024 Shenzhen Shumatt Technology Co., Ltd Tel: +8675523215133 Website : www.shumatt.com

INFIT

UMAT

UMFIT

3h

UNAT

INFIT

UNIT

AJMI

095030-6540 Injector Valve Stem G2 Series Technical File

1. 095030-6540 Injector Valve Stem Introduction

1.1. 095030-6540 Injector Valve Stem Basic Information

Title	095030-6540 Injector Valve Stem China Made New
SKU	G1F168009696FG

1.2. 095030-6540Injector Valve Stem Common Part Number

(1) Injector Valve Stem Applicable Injector Model	Mur, Hun, Hun, Hun, Hun, Hun,
Injector Valve Stem Part Number	OE Number
095000-680#	1J574-53051
095000-969#	1J500-53051

(2) Injector Valve Stem Matching Information

Vehicle Brand	Car Model	Engine Model	Production Date
KUBOTA	TRACTOR	V3800	0610
KUBOTA	INDUSTRIAL	V3800	1111
181 181 18	1. 281. 281.	221 221 22	18. 18.

(3) Injector Valve Stem Part Number Common Writing

095000-6800, 095000-6801, 095000-6802, 095000-6803, 095000-6804, 095000-6805, 095000-6806, 095000-6807, 095000-6808, 095000-6809, 095000-680#, 095000-9690, 095000-9691, 095000-9692, 095000-9693, 095000-9694, 095000-9695, 095000-9696, 095000-9697, 095000-9698, 095000-9699, 095000-969#, 095030-6540, 1J574-53051, 1J500-53051

1.3. 095030-6540 Injector Valve Stem Parameter

Adaptation System: Common Rail System

Injector Valve Stem Series: G2 Series

Injector Valve Stem Size: L65mm* 4.3mm

1.4. 095030-6540 Injector Valve Stem Specifications and Dimensions

Injector Valve StemSize: 14*1*1=25 cm³ (L*W*H=V)

Single Injector Valve Stem Weight: 20g

Injector Valve Stem Weight With Packaging: 25g

Injector Valve Stem Quality: China Made New

Injector Valve Stem Package Size: 14* 1cm *1m =14³ (L*W*H=V)

Injector Valve StemType: High Pressure Common Rail Injector Valve Stem Injector Valve Stem MOQ: 1pcs

1.5. 095030-6540 Injector Valve Stem Quality Control

(1) Injector Valve Stem Testing

All parts of the Injector valve stem have undergone electrical characteristics testing, precision testing, high temperature testing, low temperature testing, withstand pressure testing, leakage testing, durability

Mob/Whatsapp: +86 13410541523 Email : <u>ruby@shumatt.com</u> © 2024 Shenzhen Shumatt Technology Co., Ltd

testing, and various working conditions testing.

(2) Injector Valve Stem Installation

The injector value stem production and installation process is quality controlled. Our company strictly follows the standard product installation data and product installation steps for installation, such as injector stroke test, injector solenoid value tightening torque, injector nozzle tightening torque.

(3) Injector Valve Stem Inspection

The factory inspection of the injector valve stem has undergone three inspections: full inspection, random inspection, and batch inspection. Different brands of test benches are used to test the same injector valve stem for more than three times for factory inspection, and the injector valve stem installation testing environment are progressed in dust-free workshop.

1.6. 095030-6540 Injector Valve Stem Customized Service

(1) Injector Valve Stem Customized Service Coverage: Meet OEM manufacturers' customization needs for shell engraving, logo engraving, injector valve stem internal packaging, injector valve stem external packaging and labels, etc.



(2) Injector Valve Stem Customized Service Requirements:

The purchase of customized injector valve stem is no less than 10 pieces.

The purchase of customized injector valve stem boxes is no less than 1000 pieces.

• When the customized products involve the need of specify logo, the OEM manufacturer is asked to provide trademark authorization and the sample of logo image file.

▲ Once the customized injector valve stem is sold, it can't be returned or exchanged if there is no quality problems.

1.7. 095030-6540 Injector Valve Stem Package List&Size

(1) Injector Valve Stem Spare Part	ts List
------------------------------------	---------

	(I) injector	valve Stelli Spare Parts List	atter atter atter	CHIDA CHIDA CHIDA
1	No.	1	2	3
2	Image	Shumatt		
2	Name	Injector Valve Stem	Injector Valve Stem Length	Injector Valve Stem diameter
	Description	/	L65mm	Ф 4.3 mm
	T	TT TT TT	TT TT TT	TI TI TI

Mob/Whatsapp: +86 13410541523 Email : <u>ruby@shumatt.com</u> © 2024 Shenzhen Shumatt Technology Co., Ltd

▲ Minors are forbidden to use the injector assembly, O-ring, nozzle protective cover, injector house protective cover, oil return protective cover, VCI anti-rust bag, and air bubble bag to avoid personal injury.

• O-ring and washer shim are disposable installation accessories, and need to be replaced for re-installation.

▲ The nozzle protective cover, the injector house protective cover, and the oil return protective cover are recyclable accessories that can be reused.

VCI anti-rust bags and bubble bags are non-degradable materials. Please dispose of them properly after using.

▲ The injector and the installation parts should be coated with appropriate sealing oil during installation.

(2) Injector Valve Stem Package Size

			m						
H						1	1		1
H	+		-	+		t.		H	
2	卫	A	1	3	1	A		a	-

Pic No.1

No.	Name	Injector Valve Stem Package Size (cm)
15/1	Injector Valve Stem Package	14*1*1

1.8. 095030-6540Injector Valve Stem Testing Standard and Certificate

We can provide the factory quality inspection test report of each injector valve stem to ensure that each injector valve stem delivered meets the engine performance indicators.

Mob/Whatsapp: +86 13410541523 Email : <u>ruby@shumatt.com</u> © 2024 Shenzhen Shumatt Technology Co., Ltd







1.9. 095030-6540Injector Valve Stem Warranty Description

(1) Product Warranty Conditions and Instructions

INFIT

AJME

It is necessary to provide pictures, videos, or test reports detected by the injector valve stem inspection equipment as evidence to feed back to the salesman when the injector valve stem is abnormal during using.

Abnormal conditions are properly explained such as: 1.Smoke, 2. Engine shake, 3. Difficulty starting the engine, 4. Engine noise, 5. Oil leakage etc.

(2) Injector Valve Stem Warranty Coverage

Within 15 days after customer receives the 095030-6540 injector valve stem, if there is a performance failure and the product has no appearance damage, customer can choose to replace it or repair it;

If the 095030-6540 injector valve stem has performance problems during the warranty period (6-12 months), and it is confirmed that it is product's problems after testing, you can contact our salesmen to replace the same model or a reworked product with the same performance for free;

If the injector valve stem has obvious scratches, it can only be repaired and it will be returned as it is if the product is confirmed to be fault-free.

Tips: For products not covered by warranty, our company can provide paid maintenance services. For products after paid repaired, the same performance problem will have a free warranty period within 3 months from the date of repairing.

(3) injector valve stem Out of Warranty Coverage

Mob/Whatsapp: +86 13410541523 Email : <u>ruby@shumatt.com</u> © 2024 Shenzhen Shumatt Technology Co., Ltd

① The warranty period has expired.

② Injector valve stem failure caused by high temperature, high pressure, humidity, rain and snow, saline-alkali land, earthquake, and used in abnormal environment.

③ Customer disassembles or repairs the injector valve stem personally resulting in damage to the injector valve stem.

④ Injector valve stem damage caused by man-made reasons (throwing, strong magnetic field magnetization, set fire).

⑤ Injector valve stem failure or injector valve stem damage caused by non-injector valve stem design, technology, manufacturing, quality and other issues.

⑥ Injector valve stem failure due to system pressure exceeding system approved pressure.

⑦ Injector valve stem failure caused by system voltage exceeding approved voltage.

Injector valve stem failure caused by impurities (water, lead, aluminum powder, iron powder, sulfide) in the system fuel exceeding the standard requirements.

Injector valve stem failure caused by not installing according to the tightening torque specified in the vehicle engine maintenance manual (the tightening torque is too large or too small).

(1) Injector valve stem failure caused by not following the installation angle specified in the vehicle engine maintenance manual.

11 Injector valve stem failure caused by not following the cleaning requirements specified in the vehicle engine maintenance manual.

12 Injector valve stem failure caused by failure to replace consumable parts as specified in the vehicle engine maintenance manual.


13 Injector valve stem failure caused by not complying with the intake system fit clearance and exhaust system fit clearance requirements specified in the vehicle engine maintenance manual.

14 Failure to replace the consumable parts and the fitting clearance of the oil inlet system pipeline and the injector valve stem connection in accordance with the fuel intake system specified in the vehicle engine maintenance manual.

2. 095030-6540 Injector Valve Stem Technical Support

2.1. 095030-6540 Injector Valve Stem Measuring Tools

Mob/Whatsapp: +86 13410541523 Email : <u>ruby@shumatt.com</u> © 2024 Shenzhen Shumatt Technology Co., Ltd



21 21 21 21	PIC NO.3
1. Inner diameter measuring claw	7. inch/mm metric and inch conversion button
2. Limit screw	8. OFF/ON power button
3. Battery installation place	9. ZERO button
4. Ruler body	10. Push roller
5. depth measurement	11. Button battery
6. depth measurement	/ she she she she she

2.2. 095030-6540 Injector Valve Stem Measuring Steps

55	No.	1	2
i Pi	INTELLINE	SHUMATT	SHUMATT
19	Image		TITITITI CON CONTRACTOR CONTRACTO
19	INTATT SHUME	TT Stream Stream Stream	Step 2: First open the caliper (OFF/ON),
196	Description	Step 1: Choose caliper: CRT085	then return the display (ZERO) to zero ▲ The caliper must be adjusted to zero before measuring.

2.3. 095030-6540 Injector Valve Stem Installation Precautions

(1) The replacement of the injector valve stem must strictly follow the electrical system, the approved pressure of the low-pressure fuel intake system, the approved pressure of the high-pressure fuel circuit system, and fuel system replacement consumables requirements (including the low-pressure)

Mob/Whatsapp: +86 13410541523 Email : <u>ruby@shumatt.com</u> © 2024 Shenzhen Shumatt Technology Co., Ltd

- fuel circuit system filter and the high-pressure fuel circuit) specified in the vehicle engine maintenance manual.
- (2) Replacement of wearing parts of the fuel system, cleaning requirements for the connection between the fuel system and the injector valve stem, the fitting clearance of the injector valve stem connection, the installation angle and tightening torque of the injector valve stem, the fitting clearance of the intake system, and the fitting clearance of the exhaust system to ensure the service life of the engine and the normal operation of the injector valve stem.
- (3) When installing the injector valve stem on the engine, it is necessary to clean the engine block, cylinder head and other parts connected to the injector valve stem, and ensure that there is no dust, carbon deposits, water, rust spots, etc.
- (4) Before installing, check whether the injector valve stem nozzle gasket has been replaced and installed on the injector valve stem.
- (5) When installing the injector valve stem, apply lubricant between the injector valve stem, fuel nozzle sealing gasket and O-ring.
- (6) Failure to replace the gasket with a new one may result in: deformation of the tight cap of nozzle, deformation of nozzle, deformation of nozzle orifice, oil leakage and air leakage, which will cause serious damage to the injector valve stem and nozzle to break and cause damage to the engine.
- (7) When installing the injector valve stem on the engine, please carefully check the components related to the installation of the injector valve stem, such as the injector valve stem pressure plate, screw, injector valve stem rod and other accessories are not deformed, and install it in strict accordance with the operation steps of the engine maintenance manual.
- (8) It is forbidden to operate the bare injector valve stem for a long time in an environment with serious dust pollution and corrosion to iron products.
- (9) It is forbidden to operate the bare injector valve stem for a long time in a strong magnetic field environment.

2.4. Reasons For 095030-6540 Injector Valve Stem Not Working Normally

- (1) There is air in the oil circuit of the engine fuel system.
- (2) Vehicle oil pump oil supply system is not normal.
- (3) Engine common rail system oil leakage or pressure limiting valve is damaged.
- (4) There is a short circuit, cutting out and poor contact in the wiring harness connected to the injector valve stem of the vehicle.
- (5) The long-term placement of the injector valve stem causes the anti-rust oil to solidify, and the internal components are stuck or the oil holes are blocked.

▲ Before installing, carefully check whether other components in the common rail system except the injector valve stem are damaged so as to prevent the injector valve stem from not working properly after being replaced.

2.5. Causes of 095030-6540 Injector Valve Stem Being Damaged

- (1) Failure to operate correctly according to the engine maintenance manual during disassembly and assembly resulted in damage to the injector valve stem.
- (2) The fuel used for the vehicle does not meet the standard, causing damage to the injector valve stem, such as: the water content in the fuel oil exceeds the standard, iron powder, aluminum powder,

Mob/Whatsapp: +86 13410541523 Email : <u>ruby@shumatt.com</u> © 2024 Shenzhen Shumatt Technology Co., Ltd

- sulfide impurities exceed the standard, etc.
- (3) The engine is not regularly maintained according to the engine maintenance manual (please refer to the vehicle maintenance manual for the maintenance mileage). For example, failure to replace the lubricating oil of the engine system for a long time will cause abnormal wear of the engine, excessive exhaust gas volume or a large amount of carbon deposits inside the engine. The filter is not replaced during maintenance or the replaced filter cannot reach the original filter standard. All above reasons can cause damage to the injector valve stem.
- (4) The abrasion of the oil pump produces iron powder and aluminum powder enter the injector valve stem and cause damage to the injector valve stem.
- (5) The deformation and abrasion of fuel tank result in iron powder or aluminum powder entering the injector valve stem and causing damage to the injector valve stem.
- (6) The injector valve stem is damaged due to replacement or adjustment of the relevant parts of the injector valve stem. For example, the valve clearance does not meet the standard after the engine is repaired, the replacement or modification of the wiring harness connected to the injector valve stem fails to meet the original standard.
- (7) The engine is overheated and overloaded for a long time working results in damage to the injector valve stem.
- (8) The injector valve stem will be damaged naturally at the end of its working life.
- (9) The injector valve stem is magnetized (injector valve stem parts' magnetic exceeded) causing the injector valve stem to not work properly.
- A Before replacing the injector valve stem, please check the engine parts carefully according to the engine maintenance manual to avoid the injector valve stem being damaged again after replacement.

2.6. 095030-6540 Injector Valve Stem Storage Standard

(1) Choose a Suitable Storage Place

The warehouse and cargo yard where the injector valve stems are stored should be kept clean and dry, and away from the factory buildings that generate harmful gases and dust; do not mix with acid, alkali, salt and other substances; the storage place should have a good drainage system; the cargo yard should be flattened with gravel or furnace ash etc. to enhance the water permeability of the surface layer to keep the reservoir area dry.

(2) Strict Requirements of Warehousing

Strict inspections should be carried out when the injector valve stems are put into storage, the surface cleaning work should be done well to remove water traces, oil stains, ash and other dirt, remove the rust and do anti-rust treatment in time. Packaged injector valve stems must be protected from damage.

(3) Keep The Warehouse Dry And Preventing Moisture

The relative humidity is usually below 70% for the injector valve stems placed in the room, and the corrosion of the injector valve stems is significantly reduced.

Injector valve stems must be stored in the warehouse, and they are forbidden to store in the same warehouse with commodities with high water content.

(4) Stack Properly

After the injector valve stem is exposed to rain, the corrosion rate will increase significantly. The purpose of sealing is to isolate the injector valve stem from rainwater and humid air, so the warehouse window should be checked in time to avoid rainwater entering the warehouse

Mob/Whatsapp: +86 13410541523 Email : <u>ruby@shumatt.com</u> © 2024 Shenzhen Shumatt Technology Co., Ltd

If the injector valve stem package is damaged, it should be repaired or replaced; when the package is damp, the packaging material should be dried; if the original anti-corrosion and oil applied at the factory is found to be damaged or dried up, it should be cleaned and re-applied oil in time.

- It is forbidden to leave the injector valve stem exposed in the air for a long time.
- ▲ It is forbidden to store acid, alkali, salt and other substances together with the injector valve stem.
- A The unpacked injector valve stem must be rust-proof during secondary storage.

2.7. 095030-6540 Injector Valve Stem Technical Support Obtaining Methods

(1) Injector Valve Stem Technical File, visit <u>http://shumatt.com</u> to get the technical file.

(2) Injector Valve Stem Technical Videos

Facebook: Visit <u>https://www.facebook.com/hison.li</u> to get the technical videos, constantly follow can get more information.

YouTube: <u>https://www.youtube.com/channel/UCByvYBx7VjV_mAfxh_Hu-aw</u> to get the technical videos, constantly follow can get more information.

Shumatt: Visit <u>http://shumatt.com</u> to get the technical videos.

(3) Injector Valve Stem Information Query Software

TruckBook Parts EPC APP, Android/Apple App Store download and install, visit <u>http://shumatt.com</u> to get the download and installation tutorial.

(4) Search the injector valve stem test data through TruckBook Parts EPC APP.

3. 095030-6540 Injector Valve Stem Purchase and Delivery

3.1. 095030-6540 Injector Valve Stem Purchase Payment Term

Payment Terms: T/T, PayPal, Alipay, WeChat

A Please contact our salesmen for specific payment information.

3.2. 095030-6540 Injector Valve Stem Main Sales Markets

Injector Valve Stem Main Sales Markets: Asia, Europe, North America, South America, Africa etc.

3.3. 095030-6540 Injector Valve Stem Declaration Requirements

Shumatt can assist customers to provide the following documents for import customs clearance: contract, invoice, packing list, bill of lading, insurance policy, certificate of origin, etc.

3.4. 095030-6540 Injector Valve Stem Shipping Ways

Destination in China Areas: SF Express, Debon Express, the corresponding logistics company can be provided according to customer requirements in special cases.

Destinations Out of China's Areas: DHL, UPS, FedEx, TNT air, ocean or other shipping methods required by customers.

3.5. 095030-6540 Injector Valve Stem Lead time

Lead time: Send out within 3 - 7 working days after receiving payment (Except for special products and special cases).

Mob/Whatsapp: +86 13410541523 Email : <u>ruby@shumatt.com</u> © 2024 Shenzhen Shumatt Technology Co., Ltd

3.6. 095030-6540 Injector Valve Stem Logistics Time for Destination Out of China's Areas

	Country or Region of Hong Hong Hong Hong Hong Hong Hong Hong		- · ·	r, Other Countries or Australia and New Regions of Asia Zealand		Europe	America	Other Countries			
China's Mainl	China's Mainland 7 Da		iys 7 Days		Days 8 Days		8 Days	8-12 Days	7-10 Days		
JPS Logistics	Time:	e: Country or Region of Departure: China's Mainland						TT IT			
Country of Destination		mated al Time	Coun	try of Destination	Estimated Arrival Time	Cour	Country of Destination Egypt		Estimated Arrival Time		
Japan	3 [Days		UK	5-7Days	4			5-7 Days		
Turkey	5-7	Days	الم	Singapore	3 Days	UNITI .	Switzerland	i uni	5-7 Days		
Bahrain	5-7	Days	21.	Latvia	7-10 Days		New Zealand		New Zealand 7-		7-10 Days
Sri Lanka	anka 5-7 Days		s Thailand		3 Days	1	Austria		5-7 Days		
Romania	5-7	Days	الم	Vietnam 3-5 Days E		Estonia		5-7 Days			
Malaysia	3-5	Days	2	Israel	5-7 Days		Mexico		7-10 Days		
France	5-7	Days		America	5-7 Days	Unit	United Arab Emirates		ited Arab Emirates		5-7 Days
Italy	5-7	Days Neth		Netherlands	5-7 Days	Mur.	Bengal		7-10 Days		
Lebanon	5-7	Days		Philippine	3-5 Days		Greece		7-10 Days		
South Korea 3		3 Days		Spain	5-7 Days	17	Myanmar		5-7 Days		
Canada 5-7		Days	Germany		many 5-7 Days		Saudi Arabia		7-10 Days		
Portugal	Portugal 5-7 Da		Australia		5-7 Days	7 Days South Africa		а	7-10 Days		
Denmark	Denmark 5-7 Day			Belgium	5-7 Days	TIT	Ukraine		7-10 Days		
India 7) Days	shun	Qatar	7-10 Days	Du.	Poland	SHUM	5-7 Days		
Indonesia	3-5	Days		Morocco	7-10 Days		Pakistan		7-10 Days		
Kuwait	7-10) Days			T	TIP					

The logistics time is for reference only, subjects are according to the actual arrival.

3.7. 095030-6540 Injector Valve Stem Packing

Domestic Express Packaging: Usually wrapped in waterproof scotch tape, such as picture No.4. **International Express Packaging:** Wrapped with waterproof yellow tape after wrapping the black protective film, such as picture No. 5.

Pallet Shipping: Use fumigation free and recycling trays that meet export requirements, and use white wrapping protective film to wrap and bind with cable ties for the outside, such as picture No. 6, also, the products can be packaged according to customers' requirements.

The packing tray is made of plastic and can be recycled.

▲ Transparent tape, yellow tape, black wrapping protective film, white wrapping protective film are non-degradable materials, please dispose of them properly.

A Minors are prohibited from using transparent tape, yellow tape, black wrapping protective film, and white wrapping protective film to avoid personal injury.

Mob/Whatsapp: +86 13410541523 Email : <u>ruby@shumatt.com</u> © 2024 Shenzhen Shumatt Technology Co., Ltd



Mob/Whatsapp: +86 13410541523 Email : <u>ruby@shumatt.com</u> © 2024 Shenzhen Shumatt Technology Co., Ltd

4. Company Information

- Office Locations
- Global Exhibitions

4.1. Company Introduction
Chinese Name: 深圳市舒马特科技有限公司
English Name: Shenzhen Shumatt Technology Co., Ltd
Injector Valve Stem Manufacturer: Shenzhen Shumatt Technology Co., Ltd

- **Mob Phone/WeChat:** +86-13410541523
- **HK Telephone:** +852-67653519
- Telephone: +86-755-23215133
- Email: ruby@shumatt.com
- Website: www.shumatt.com

Shenzhen Office: 11-12, Floor 14, Building 13, Qinchengda Building, Exit A, Honglang North Subway Station, Bao'an District, Shenzhen, China Mainland

Pic No. 7

Shenzhen Office: Exit C, Qiao Touxi Metro Station, NO. 66 Chongqing Road, Fuhai Avenue, Bao'an District, Shenzhen, China Mainland

- Hong Kong Office: Jianfa Street Industrial Zone, Tuen Mun, New Territories, Hong Kong, China
- After-sales Service Address: Please contact our salesmen to obtain and provide the corresponding

Mob/Whatsapp: +86 13410541523 Email : <u>ruby@shumatt.com</u> © 2024 Shenzhen Shumatt Technology Co., Ltd

product maintenance reasons (Reference: <u>1.9. 095030-6540 Injector Valve Stem Nut Warranty</u> Instructions)

No.	Name	WeChat/WhatsApp	Email	Facebook	YouTube
1	Ruby	+86-13410541523	ruby@shumatt.com	Hison Li	Hison Li
2	lvy	+86-18025309821	sales@shumatt.com	Ivy Shumatt	Shumatt IVY
3	Rebecca	+86-18025349821	sales01@shumatt.com	Rebecca Shumatt	ShumattRebecca
4	Janny	+86-18028749821	sales02@shumatt.com	Janny shumatt	Janny Shumatt
5	Sam	+86-13316859821	Sales8@shumatt.com	Shumatt Sam	Sam Shumatt
6	Natalie	+86-18938945856	sales15@shumatt.com	Shumatt Natalie	Lin Natalie
7	Ada	+86-1342286353	sales5@shumatt.com	Shumatt Ada	Ada Shumatt
8	Hison Li	+86-18318811871	web@shumatt.com	Hison Li	Hison Li
9	Mecca	+86-18938948618	sales11@shumatt.com	Shumatt Mecca	Shumatt Mecca
10	Eric	+86 18319033618	sales3@shumatt.com	21. 21.	31. 31
11	Wayne (Joaquí n enespañol)	+86-13316959821	wayne@shumatt.com	shumattwayne	Wayne Shumatt
12	Sylvia	+86 18312499884	sales6@shumatt.com	SHOW SHOW	SHUM SI

5. Copyright Statement

The copyright of any contents in this file "095030-6540 Injector Valve Stem G2 Series Technical File" (including but not limited to parameters, data, text, charts, images, sounds, videos, etc.) belongs to Shenzhen Shumatt Technology Co., Ltd. Without the prior written permission of Shenzhen Shumatt Technology Co., Ltd., you are not allowed to modify, duplicate, republish any content in "095030-6540 Injector Valve Stem G2 Series Technical File" in any way. At the same time, any conditions to spread, repost, display the contents of "095030-6540 Injector Valve Stem G2 Series Technical File" should indicate the source of the quoted article, Shenzhen Shumatt Technology Co., Ltd. Any actions failure to follow above conditions violate the "Copyright Law of the People's Republic of China" and other laws and regulations as well as relevant provisions of international conventions.

Mob/Whatsapp: +86 13410541523 Email : <u>ruby@shumatt.com</u> © 2024 Shenzhen Shumatt Technology Co., Ltd